Ohio EPA - Daily Discharge Monitoring Report - Form 4500

SUBMISSION ID:

160273

STATUS:

Original

FACILITY: LOCATION:

Intersect St Rte 148 and Rd 86 ALLEDONIA, OH 43902

Ohio Valley Coal Co Powhatan No 6 Mine * PERMIT NUMBER: 002

01L00046*DD

COUNTY:

STATION CODE: MONITORING PERIOD:

2011-02-01 To: 2011-02-28 TraDet

REPORTING LAB:

William Thompson

DISTRICT:

Belmont SEDO

ANALYST: NO DISCHARGE INDICATOR:

DADASAETED	CDOD 5 1					Y	T**
PARAMETER PARAMETER CODE	CBOD 5 day 80082	pH 00400					
UNITS	mg/l	S.U.	<u> </u>				
FREQUENCY	1/2 Weeks	I/Month					
SAMPLING TYPE	Grab	Grab					<u></u>
2011-02-01	}	ļ	ļ				
2011-02-02	1.26	7.3					
2011-02-03							
2011-02-04							
2011-02-05	<u></u>	L					
2011-02-06							
2011-02-07							
2011-02-08							
2011-02-09							
2011-02-10							
2011-02-11							
2011-02-12							
2011-02-13							
2011-02-14							
2011-02-15							
2011-02-16	1.71						
2011-02-17							<u> </u>
2011-02-18							
2011-02-19							
2011-02-20							
2011-02-21							
2011-02-22							
2011-02-23							
2011-02-24							
2011-02-25				··· ··· - 			
2011-02-26			<u> </u>				
2011-02-27			1				· · · · · · · · · · · · · · · · · · ·
2011-02-28			 		— 		·· ··············
Minimum	1.26	7.3					
Maximum	1.71	7.3					
Average	1.485		<u> </u>				
Count	2	1	<u></u>				
Name of Responsible Officia or Authorized Representative	I certify under the penalty of law that I have personally examined and am familiar with the information submitted herein and based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the						Submission Date/Time
Cody Mozena	submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment. Lucy M. Maynow Lucy M. Maynow						2011-03- 12 11:03

https://ebiz.epa.ohio.gov/edwr.web/page/report/viewWithXslt.do?actType=viewWithXslt... 3/12/2011

Page 3